


GET THE RIGHT TRANSMISSION FLUID



LISTEN UP. DO **NOT** MIX OTHER TYPES OF FLUIDS, LIKE DEXRON III OR VI, IN THE RG31'S TRANSMISSION.

THAT CAUSES UNNECESSARY WEAR-AND-TEAR AND PERFORMANCE PROBLEMS.



IF YOU'VE USED THE WRONG TRANSMISSION FLUID IN AN MRAP RG31 VEHICLE, DRAIN IT!

REFILL IT WITH TES-295 FLUID.

ALSO, MAKE SURE YOU REPLACE THE TRANSMISSION FLUID'S FILTERS, NSN 2910-01-508-1913 AND 4330-01-520-4832, BEFORE YOU REFILL THE TRANSMISSION.

